

Millermatic 355 Software Update Release Notes

Version 1.4 – May 2026

New Software Versions

User Interface – 87517

Release Notes

- Fix an issue with numerical menu items causing the UI to reset when trying to set high values (introduced on v1.3 – UI version 87447)
-

Version 1.3 – April 2026

New Software Versions

User Interface – 87447

Weld Controller – 87447

Weld Programs – 0x7BD8AD5B

Release Notes

- Updated aluminum programs
 - Allow locks and limits ranges to go to 100%
 - Added System Menu setting for 10-pin gun override
 - Reduced burnback times
 - Various improvements and optimizations
-

Version 1.2 – April 2024

New Software Versions

Weld Controller – 83685

Release Notes

- Fixed issue allowing undesired transition through burnback when run-in is cancelled
-

Version 1.1 – November 2023

New Software Versions

User Interface – 82134

Weld Controller – 82134

Graphics – 0x5DF6B757

Weld Programs – 0x2E142B59

Release Notes

- Updates to weld starts to improve aluminum performance
- Enabling adjustable hotstart for all MIG and Pulse MIG wires (was previously aluminum only)
- Reduced minimum WFS to 25 IPM to allow for slower run-in
- Added System Menu setting for Auto-Set disable
- Added serial number and software version info to exported USB logs

- Changed TIG Trigger Error message to 10-Pin Trigger Fault
 - Bug fixes related to Invalid Weld Data error occurring during machine setup.
 - Bug fixes related to errors occurring during operation with remote pot WFS adjustment disabled
-

Version 1.0

Software Versions

User Interface – 71957

Weld Controller – 71957

Graphics – 0xF4363C17

Weld Programs – 0x5A5E1589

Release Notes

- Product launch