



PM-272149A

2023-08

Processes





Multiprocess Welding

Description

Accessory

ArcReach[®] Stick/TIG Remote



For product information,
Owner's Manual translations,
and more, visit


www.MillerWelds.com

PARTS MANUAL

File: Multiprocess



SECTION 1 – PARTS LIST



274884-A

Figure 1-1. ArcReach Stick/TIG Remote Assembly

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 1-1. ArcReach Stick/TIG Remote Assembly				
1		272528	Lens, Front Panel Pendant Ctrl	1
2		258838	Screw, 008-32x .37 Pan Hd-Phl Stl Pld Zc Lkg Patch	2
3		273851	Washer, Flat Seal No 8 X .500 od	2
4		272128	Conn, Tw Lk Insul Fem(Tweco/Lenco Typ)Lc-40Hd 2/0	1
5		600322	Cable, Weld Cop Strd No 2/0 Ep Rubber Jacket 600V	18 in.
6		274542	Nut, 006-32 Rubber .452Dia X .499l X .312Hole	8
7		273033	Cover, Power Cable Assy	2
8		602072	Screw, 006-32x .62 Hexwhd-Slt Stl Pld Blk	8
9		273032	Cover, Power Clamp Assy	1
10		268286	Conn, Tw Lk Insul Male(Tweco/Lenco Type)Lc-40Hd 2/0	1
11		273268	Cable, Sensing (Includes)	1
		258058	Wire, Strd 10Ga Blk 600V 125C 105x30 Poe .216od	15.5 Ft
		208820	Clamp, Work	1
		272534	Label, Warning Electric Shock/Volt Sense Clamp	1

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Notes

Miller Electric Mfg. LLC

An Illinois Tool Works Company
1635 West Spencer Street
Appleton, WI 54914 USA

International Headquarters-USA

USA Phone: 920-735-4505 Auto-Attended
USA & Canada FAX: 920-735-4134
International FAX: 920-735-4125

For International Locations Visit
www.MillerWelds.com

